



BMW 3: 1GNP801			
Vinnumber:	WBA3Y11020D376442	Versionname:	3 GRAN TURISMO 318dA
First Registrationdate:	19/03/2014	Fiscalpower:	136PK Aut.
Expertise Mileage:	193253	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back		
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options			
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear				
	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 1 mm	Fr.R.	Michelin: 1 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment	
Total cost ex VAT	544,80
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



GPS, Crack, E - Replace	0,00
-------------------------	------



Seat cover F L, Crack, Acceptable 0,00



Front bumper, Bump(s), LI - Repair and paint (complete) 259,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

