



<b>BMW 3: 1FEY450</b>			
Vinnumber:	<b>WBA3K910X0F930542</b>	Versionname:	<b>3 TOURING 316d 116PK</b>
First Registrationdate:	<b>11/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>98711</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2805</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/60/16/92 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>926,78</b>
<b>Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>



<b>Wing R R, Bump(s), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Door R R, Scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>



Bumper R, Difference in color, Acceptable	0,00
---	------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08
--	--------

