


BMW 316 TOURING: 1HJH402

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WBA3K91070F935875 | Versionname: | 3 TOURING 316d 116PK |
| First Registrationdate: | 1/08/2014 | Fiscalpower: | |
| Expertise Mileage: | 188271 | Power Kw: | 85 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | + 9000 KM | Parking lot: | 3811 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|----------------------------------|----------------------|----------------------|
| Radio CD | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| GPS storage | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | Tow bar fixed |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining artificial leather | | |
| Type of climate control | Autom climate control | | |
| Level control | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/60/16/96 H LightMetal | | | |
| Winter tyres: | Fr.L. | Semperit: 6 mm | Fr.R. | Semperit: 6 mm |
| | Re.L. | Semperit: 5 mm | Re.R. | Semperit: 5 mm |

Assistance equipment

| | | | |
|---------------------------------------|------------|------------|-------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 0,00 |
| Wing R R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Door F R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Seat cover F L, Damaged, Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Door R R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Front bumper, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |