



BMW 218: 1KNY579

Vinnumber:	WBA2C11010V518445	Versionname:	ACTIVE TOURER
First Registrationdate:	5/06/2015	Fiscalpower:	
Expertise Mileage:	196150	Power Kw:	100
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3129
Maintenance:	OVER 15000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	Tow bar removable
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	No
------------	------------	------------	-----------

Total cost ex VAT **633,08**

Door F R, Scratch(es), Acceptable **0,00**



Door panel R L, Hole, Smart repair **110,64**



Boot cover, Tear, E - Replace 50,00



Compressor, Missing, E - Replace 75,00



Door panel R R, Hole, Smart repair 110,64



Door R R, Scratch(es), Acceptable 0,00



Floor covering R, Stain, Cleaning 50,00



Ceiling, Stain, Cleaning 25,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Bump(s), Acceptable 0,00



Seat cover F L, Worn, P - Check 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

