



MERCEDES CLA: 1LFT171

Vinnumber:	WDD1173121N282095	Versionname:	1.5 CLA 180 CDI AMG LINE
First Registrationdate:	16/09/2015	Fiscalpower:	
Expertise Mileage:	130321	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 103 DAGEN SERV A	Parking lot:	4704
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	710,00
-------------------	---------------

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	-------------

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Chemical polution, LI - Repair and paint (complete) 308,20



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display