


**BMW X1: 1HHK088**

Vinnumber:	<b>WBAVN71090VX12313</b>	Versionname:	<b>X1 sDrive18d 136PK</b>
First Registrationdate:	<b>24/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>111906</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4327</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/94 H Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 3,5 mm</b>	Fr.R.	<b>Bridgestone: 3,5 mm</b>
	Re.L.	<b>Bridgestone: 3,5 mm</b>	Re.R.	<b>Bridgestone: 3,5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>617,44</b>
-------------------	---------------

Wheel cover R L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	<b>115,56</b>
--	---------------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>290,08</b>
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), Acceptable

0,00

*No pictures to display*