



CITROËN GRAND C4 Picasso: 1FJC020

Vinnumber:	VF7UA9HR8DJ681345	Versionname:	GR.C4 PICAS. e-HDi
First Registrationdate:	12/07/2013	Fiscalpower:	Bus.GPS FAP BMP 112PK
Expertise Mileage:	159204	Power Kw:	82
Bodytype:		Body color:	SABLE
Gearbox:	Automatic	Body color:	Grey
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	4727
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Bridgestone: 2 mm	Re.R.	Bridgestone: 2 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 325,16

Inner door handle F L, Worn, Acceptable 0,00

No pictures to display

Roof rail L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Bumper moulding R Mid, Scratch(es), Le - Replace and paint 100,00



Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F L, Scratch(es), Le - Replace and paint 100,00



Roof rail R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bike rack, Not original part, P - Check	0,00



Rocker panel inner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), It - Spot repair	125,16

