



BMW X4: HL8964			
Vinnumber:	WBAXX11000R37376	Versionname:	2.0 XDRIVE20D (140KW)
First Registrationdate:	21/10/2015	Fiscalpower:	4WD
Expertise Mileage:	68861	Power Kw:	140
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4302
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/60/17/99 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment	
Runflat	Yes
Total cost ex VAT	792,04
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	410,02





Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Roof pillar L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------

