


CITROËN GRAND C4 PICASSO: 1KTK009

Vinnumber:	VF73A9HC8FJ609734	Versionname:	1.6 E-HDI 115 MAN6 BUSINESS GPS
First Registrationdate:	30/06/2015	Fiscalpower:	
Expertise Mileage:	181331	Power Kw:	85
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4608
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	901,12
-------------------	--------

Backrest cover F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display




















Door R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roof pillar R, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)		290,08
		
Armrest L, Worn, Acceptable		0,00
		
Wing R R, Bump(s), PDR - Knock out without painting		63,00
		
Floor covering F L, Hole, E - Replace		252,00
		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Bump(s), PDR - Knock out without painting		122,40
		
		
Door panel R R, Scratch(es), Smart repair		110,64
		
Backrest cover F L, Scratch(es), Acceptable		0,00
		
Door frame R L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		