



FORD Fiesta: SM8214

Vinnumber:	WF0DXXGAKDEL75764	Versionname:	FIESTA BER Trend ECONetic S/S 95PK
First Registrationdate:	6/01/2016	Fiscalpower:	
Expertise Mileage:	187676	Power Kw:	70
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3610
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/14/82 T Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	3793,61
-------------------	---------

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	246,56
---	--------



Door R L, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------






Door F R, Accident, Le - Replace and paint 894,81



Door F L, Scratch(es), LI - Repair and paint (complete) 254,68



Door frame R L, Bump(s) and scratch(es), It - Spot repair 115,56



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover R L, Broken, E - Replace 24,00



Interior, Dirty, Cleaning 25,00



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 385,20





Windscreen - Stone chip(s), Windscreen repair 58,80

windscreen, Stone chip(s), windscreen repair 50,00



Rearview mirror R complete, Damaged, Le - Replace and paint 259,00



De-icer nozzle internal L, Missing, E - Replace 153,60



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 169,44



Reflector, Broken, E - Replace 25,00



Wheel cover F R, Damaged, E - Replace 24,00



Roof pillar R, Scratch(es), It - Spot repair 115,56




Outer door handle F R, Scratch(es), LI - Repair and paint (complete) 115,56



Wing F R, Scratch(es), LI - Repair and paint (complete) 176,14





Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	241,34
---	--------

