



**RENAULT CAPTUR: 1LSY767**

|                                   |                          |              |   |
|-----------------------------------|--------------------------|--------------|---|
| Vinnnumber:                       | <b>VF12RBR1C54287559</b> | Versionname: | <b>1.5 ENERGY DCI 110<br/>EXTREM ECO2</b> |
| First Registrationdate:           | <b>26/11/2015</b>        | Fiscalpower: |   |
| Expertise Mileage:                | <b>75977</b>             | Power Kw:    | <b>81</b>                                 |
| Bodytype:                         |                          | Body color   | <b>Grey</b>                               |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                            |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                          |
| Fueltype:                         | <b>Diesel</b>            |              |   |
| Number of seats                   | <b>5</b>                 |              |   |
| Number head rests                 | <b>5</b>                 |              |   |
| Rims summer                       | <b>Aluminium</b>         |              |   |
| Category                          | <b>Passenger Car</b>     |              |   |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |   |

**Options**

**Limited Technical Inspection**

**Degree of wear**

|               |                                  |                    |       |                    |
|---------------|----------------------------------|--------------------|-------|--------------------|
|               | <b>205/55/17/91 V LightMetal</b> |                    |       |                    |
| Summer tyres: | Fr.L.                            | <b>Kumho: 4 mm</b> | Fr.R. | <b>Kumho: 4 mm</b> |
|               | Re.L.                            | <b>Kumho: 7 mm</b> | Re.R. | <b>Kumho: 7 mm</b> |

**Assistance equipment**

|                               |      |
|-------------------------------|------|
| Total cost ex VAT             | 0,00 |
| Bodywork, Accident, No repair | 0,00 |



