



MERCEDES A: 1HAN820			
Vinnumber:	WDD1760121V015747	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	80687	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1714
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Steering wheel multifunctional	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Headlighting Halogen
Type of Lining	Lining semi-leather
Type of climate control	Manual climate control
	Rear parking sensors

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/45/17/91 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes

Total cost ex VAT	1398,35
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



GPS disc, Damaged, E - Replace	275,00
--------------------------------	--------



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

