



<b>NISSAN QASHQAI: 1KJG639</b>			
Vinnumber:	<b>SJNFAAJ11U1372610</b>	Versionname:	<b>1.5 DCI TEKNA</b>
First Registrationdate:	<b>11/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>161377</b>	Power Kw:	<b>81</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2502</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Seats electric F L	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting LED</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>225/45/19/96 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 5 mm</b>	Fr.R.	<b>Dunlop: 5 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

<b>Assistance equipment</b>	
Total cost ex VAT	568,56
Rearview mirror L complete, Damaged, E - Replace	168,00



Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Aluminum F.R. ...	05,00
-------------------	-------

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Rust, Acceptable 0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display