


**PEUGEOT 508: 1HFX998**

|                                    |                          |              |                                |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnnumber:                        | <b>VF38EAHXMEL025965</b> | Versionname: | <b>508 SW Allure STT 150PK</b> |
| First Registrationdate:            | <b>10/07/2014</b>        | Fiscalpower: |                                |
| Expertise Mileage:                 | <b>154171</b>            | Power Kw:    | <b>110</b>                     |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>White</b>                   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                 |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3629</b>                    |
| Number of doors:                   | <b>5</b>                 |              |                                |
| Number of seats:                   | <b>5</b>                 |              |                                |
| Number head rests:                 | <b>5</b>                 |              |                                |
| Rims summer:                       | <b>Aluminium</b>         |              |                                |
| Category:                          | <b>Passenger Car</b>     |              |                                |
| Oil level:                         | <b>OK</b>                |              |                                |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                |

**Options**

|                              |                              |                       |                      |
|------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD                     |                              | Seats electric F L    |                      |
| GPS storage                  |                              | Seats electric F R    |                      |
| GPS storage                  | <b>HD</b>                    | Panoramic roof        |                      |
| Windows electric F           |                              | Central consol F      |                      |
| Windows electric R           |                              | Luggage cover         |                      |
| Cruise Control               |                              | Front parking sensors |                      |
| Steering wheel multifunction |                              | Rear parking sensors  |                      |
| Seats F heated               |                              | Type of Tow bar       | <b>Tow bar fixed</b> |
| Radio multimedia             |                              |                       |                      |
| Type of headlighting         | <b>Headlighting Xenon</b>    |                       |                      |
| Type of GPS                  | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining               | <b>Lining leather</b>        |                       |                      |
| Type of climate control      | <b>Autom climate control</b> |                       |                      |
| Head-up Display              |                              |                       |                      |
| Sport seats                  |                              |                       |                      |

**Limited Technical Inspection**

|                     |           |                     |               |
|---------------------|-----------|---------------------|---------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b>    |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>     |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>NOT OK</b> |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>     |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>     |
|                     |           | Lighting            | <b>OK</b>     |
|                     |           | Wiperblades         | <b>OK</b>     |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/55/17/98 V LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |         |
|-------------------|---------|
| Total cost ex VAT | 3078,13 |
|-------------------|---------|

|                                   |      |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                                       |        |
|---------------------------------------|--------|
| Protection plate M, Tear, E - Replace | 129,60 |
|---------------------------------------|--------|



|  |       |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Bump(s), Le - Replace and paint 712,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Mirror side blinker R, Scratch(es), Acceptable 0,00

No pictures to display  
Engine protective plate, Tear, E - Replace 117,45



Foglight R, Not original part, E - Replace 138,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Damaged, E - Replace 235,20



Bumper R, Bump(s), E - Replace 415,20



Sill outer L, Bump(s), LI - Repair and paint (complete) 502,50



Armrest F Mid, Damaged, E - Replace 331,38

