


MERCEDES GLK: 1DMT370

Vinnnumber:	WDC2049841F950557	Versionname:	GLK 220 CDI BE 4M 163PK Aut.
First Registrationdate:	26/06/2012	Fiscalpower:	
Expertise Mileage:	71197	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 15 DAGEN	Parking lot:	3124
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/60/17/102 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Compressor	Yes
-----------------------	------------	------------	------------

Total cost ex VAT	1491,80
-------------------	---------

Wing R L, Bad repair, Paint	0,00
-----------------------------	------



Dashboard, Scratch(es), Smart repair	110,64
--------------------------------------	--------



Ashtray, Scratch(es), E - Replace 15,00



Rearview mirror housing L, Scratch(es), Smart repair 110,64



Sill outer L, Scratch(es), It - Spot repair 115,56



Bonnet, Chemical pollution, LI - Repair and paint (complete) 348,09



Side window trim R L, Scratch(es), Smart repair 110,64




Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Brand badge R, Missing, E - Replace 35,00



Door R L, Bad repair, Acceptable 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02

