



MITSUBISHI ASX: 1FIQ652			
Vinnnumber:	JMBXJGA6WDZ407149	Versionname:	ASX 2WD Instyle 115PK
First Registrationdate:	9/07/2013	Fiscalpower:	
Expertise Mileage:	110377	Power Kw:	85
Bodytype:	SUV	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4226
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
GPS storage	HD	Seats electric F L	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/61/17/96 H LightMetal			
Summer tyres:	Fr.L.	Yokohama: 2,3 mm	Fr.R.	Yokohama: 2,3 mm
	Re.L.	Yokohama: 4 mm	Re.R.	Yokohama: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			381,35
Bonnet, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Bump(s), PDR - Knock out without painting			63,00



Trunk lid covering R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Bump(s), Acceptable			0,00

<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), LI - Repair and paint (complete)		318,35
		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		