


MERCEDES C: 1EZW976

Vinnumber:	WDD2040011A865737	Versionname:	C BER 200 CDI BE
First Registrationdate:	2/05/2013	Fiscalpower:	Optimum Ed.St/St 136PK
Expertise Mileage:	91041	Power Kw:	100
Bodytype:	Berline	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4522
Maintenance:	BINNEN 25 DAGEN		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/16/89 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1006,93
-------------------	----------------

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	---------------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door panel F L, Damaged, E - Replace	114,00
--------------------------------------	---------------



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Burned, Smart repair 64,32



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display