



TOYOTA GRAND PRIUS+: 1PGN641

Vinnnumber:	JTDZS3EU10J009010	Versionname:	1.8 VVT-I HYBRID ACTIVE
First Registrationdate:	30/06/2016	Fiscalpower:	AUTO
Expertise Mileage:	30491	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2602
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 V Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Total cost ex VAT	1257,71
Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00





Door panel R R, Scratch(es), E - Replace 114,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Missing, E - Replace 0,00



Bumper F M, Bump(s) and scratch(es), Smart repair 110,64



Centre console, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 30,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



R Pillar right, Bump(s) and scratch(es), It - Spot repair 115,56



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler R, Scratch(es), LI - Repair and paint (complete) 115,56



Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display