



## PEUGEOT 5008: 1GFP114

Vinnumber:	<b>VF30A9HD8ES008234</b>	Versionname:	<b>5008 Allure 115PK</b>
First Registrationdate:	<b>27/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>111755</b>	Power Kw:	<b>84</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3426</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/50/1/95 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Pirelli: 6 mm</b>	Re.R.	<b>Pirelli: 6 mm</b>

## Assistance equipment

Compressor **Yes**Total cost ex VAT **2021,88**Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) **308,20**

Bumper R, Scratch(es), LI - Repair and paint (complete)

**211,80**



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Protection plate M, Tear, E - Replace 74,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00





Rear spoiler, Scratch(es), LI - Repair and paint (complete) 115,56



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Headlight protector F L, Scratch(es), Smart repair 110,64



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

