



OPEL Astra: 1ELF562	
Vinnnumber:	WOLPD8EW8D8021215
Versionname:	ASTRA BRE ecoFLEX Enjoy St/St 110PK
First Registrationdate:	11/01/2013
Fiscalpower:	
Expertise Mileage:	163237
Power Kw:	81
Bodytype:	Break
Body color:	Black
Gearbox:	MAN 6 VIT
Paint type:	Metalic
Transmission:	
Rims summer:	Steel
Fueltype:	Diesel
Oil level:	OK
Battery functioning:	Yes
Parking lot:	3322
Number of doors:	5
Number of seats:	5
Number head rests:	5
Rims summer:	Steel
Category:	Passenger Car
Oil level:	OK

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/60/16/95 V Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Spare wheel	Yes
Jack	Yes

Total cost ex VAT	3061,82
Door R R, Bad repair, Acceptable	0,00



Sunblind R, Damaged, E - Replace	150,00
----------------------------------	---------------



Door F L, Bad repair, Acceptable	0,00
----------------------------------	-------------



Interior, Smell, Ozone treatment 152,58



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Bonnet, Bump(s), Acceptable 0,00

No pictures to display


Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover R L, Damaged, E - Replace 30,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

