









# BMW 3: 1FJG064

Vinnumber: WBA3D91070F406324 First Registrationdate: 15/07/2013 Expertise Mileage: 146139 Bodytype: Gearbox: MAN 6 VIT Transmission: Back Fueltype: Diesel Maintenance ок Battery functioning Yes Number of doors 4 Number of seats 5 Number head rests 5 Rims summer Aluminium Category Passenger Car Oil level OK

Versionname: 3 BER 316d 116PK

Fiscalpower: Power Kw: 85 Body color Black Paint type Metalic Rims summer Aluminium Oil level OK Parking lot 3814

#### Options

Radio CD Central consol F GPS storage GPS storage

HD Rear parking sensors Type of Tow bar

Tow bar removible

Windows electric F Windows electric R Cruise Control

Steering wheel multifunctional

Type of headlighting Headlighting Halogen Type of GPS GPS big screen color Type of Lining Lining leather Type of climate control **Autom climate** control

# Limited Technical Inspection

Airco functioning	ок	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	ок	Sound engine	ок
Engine startingtime	ок	Clutch test	ок
Exhaust gass	ок	Wiper fluid level	ОК
Handbrake	ок	Transmission	ОК
		Lighting	ок
		Wiperblades	ок

### Degree of wear

225/50/17/94 W LightMetal Fr.R. Summer tyres: Fr.L. Bridgestone: 7 mm Bridgestone: 7 mm Re.L. Re.R. Goodyear: 7 mm Goodyear: 7 mm

#### Assistance equipment

Runflat	Yes
Total cost ex VAT	189,00
Door R R, Bump(s), PDR - Knock out without painting	63,00





Door F R, Bump(s	DDD Knock	out without	nainting
Door I IN, Dulliple	, I DIV - MINOCK	Out williout	paining



Wing R R, Bump(s), PDR - Knock out without painting

63,00



