



SKODA Octavia: 1DNR290			
Vinnnumber:	TMBCT21Z3D8007691	Versionname:	OCTAVIA BER Ambition
First Registrationdate:	2/07/2012	Fiscalpower:	DPF DSG 105PK Aut.
Expertise Mileage:	141944	Power Kw:	77
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4627
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Alarm			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6,5 mm	Re.R.	Goodyear: 6,5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1061,23
Maintenance book, Missing, E - Replace			0,00

<i>No pictures to display</i>			
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)			308,20



Rearview mirror housing L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing R, Broken, E - Replace			45,00



Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Door frame F L, Bump(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display