


**RENAULT Megane: 1HJS280**

Vinnumber:	<b>VF1KZ0R0251396475</b>	Versionname:	<b>MEGANE GT TomTom Edition 95PK</b>
First Registrationdate:	<b>4/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>185050</b>	Power Kw:	<b>70</b>
Bodytype:		Body color	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>NOT OK</b>	Parking lot	<b>4602</b>
Maintenance	<b>UITVOEREN</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Fulda: 6 mm</b>	Fr.R.	<b>Fulda: 6 mm</b>
	Re.L.	<b>Fulda: 7 mm</b>	Re.R.	<b>Fulda: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1480,31</b>
-------------------	----------------


Wheel cover F L, Damaged, E - Replace	<b>30,00</b>
---------------------------------------	--------------



Door R R, Scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---	---------------



Seat belt F L, Damaged, P - Check 0,00



Door frame F R, Bump(s) and scratch(es), It - Spot repair 163,56

No pictures to display

Maintenance, Maintenance, Execute 0,00



Aerial, Missing, E - Replace 15,00



Luggage space cover, Damaged, E - Replace 240,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Windscreen, Damaged, E - Replace 487,20



Bumper corner R R, Scratch(es), It - Spot repair 115,56



Door moulding Lower F L, Scratch(es), Acceptable 0,00

No pictures to display