



BMW 3: 1FXC181

Vinnumber:	WBA3D91080J413165	Versionname:	3 BER 316d 116PK
First Registrationdate:	25/11/2013	Fiscalpower:	
Expertise Mileage:	155988	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2814
Maintenance:	SERVICE IN 24000KM 11 2018		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	
GPS storage		
Windows electric F		
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT **158,00**

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) **95,00**





Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door F L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Wing F L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display