



VOLKSWAGEN Golf: 1EWR398			
Vinnnumber:	WVWZZZAUZDP068446	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	9/04/2013	Fiscalpower:	
Expertise Mileage:	177986	Power Kw:	77
Bodytype:		Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1314
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		


Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Emergency spare wheel	Yes Jack Yes
Total cost ex VAT	481,50
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	481,50





Maintenance book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	