


TOYOTA GRAND PRIUS+: 1LEC573

Vinnnumber:	JTDZS3EUX0J002170	Versionname:	1.8 VVT-I HYBRID LOUNGE
First Registrationdate:	2/09/2015	Fiscalpower:	AUTO
Expertise Mileage:	103460	Power Kw:	73
Bodytype:	MPV	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2821
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/17/91 V LightMetal			
Summer tyres:	Fr.L.	Toyo: 6 mm	Fr.R.	Toyo: 6 mm
	Re.L.	Toyo: 6 mm	Re.R.	Toyo: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	231,12
-------------------	--------

Door frame R R, Bump(s), It - Spot repair	115,56
---	--------






Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>		
Door frame R L, Bump(s), It - Spot repair		115,56
		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Internal Boot Lining R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Steering wheel, Worn, P - Check		0,00
		
Rear window, Not original part, Remove lettering		0,00
		
Centre console, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		