



VOLVO V40: 1FME880			
Vinnnumber:	YV1MV8481E2094497	Versionname:	V40 D2 Base 115PK
First Registrationdate:	14/08/2013	Fiscalpower:	
Expertise Mileage:	77104	Power Kw:	84
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3820
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Seats electric F L
GPS storage HD	Panoramic roof
GPS storage	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting Headlighting Halogen	
Type of GPS GPS big screen color	
Type of Lining Lining leather	
Type of climate control Manual climate control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/50/17/93 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			903,60
Door F R, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00





Headlight R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror L complete, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Backrest cover F L, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Boot carpet, Missing, E - Replace 100,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rear spoiler, Bad repair, Paint 0,00

