



## VOLKSWAGEN Touran: 1HDF327

Vinnumber:	<b>WVGZZ1TZEW102248</b>	Versionname:	<b>TOURAN Trendline BMT St&amp;St 7pl.105PK</b>
First Registrationdate:	<b>24/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>66695</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4623</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

## Assistance equipment

Spare wheel	<b>No</b>	Jack	<b>No</b>
-------------	-----------	------	-----------

Total cost ex VAT	<b>210,53</b>
Wheel cover R R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Tyre repair kit, Missing, E - Replace	<b>210,53</b>
<i>No pictures to display</i>	
Bumper R, Chemical polution, Acceptable	<b>0,00</b>
<i>No pictures to display</i>	