


FORD S Max: 1HFS969

Vinnnumber:	WF0SXXGBWSEU68431	Versionname:	S-MAX ECO Tit.Style DPF PS 136PK Aut.
First Registrationdate:	9/07/2014	Fiscalpower:	
Expertise Mileage:	196241	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4826
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	No
Total cost ex VAT			535,60
Bonnet, Chemical polution, Acceptable			0,00
<i>No pictures to display</i>			
Wing F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Protection plate M, Tear, E - Replace			74,00



Windscreen, Scratch(es), E - Replace			0,00
--------------------------------------	--	--	------



Tyre repair kit, Missing, E - Replace 250,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror glass L, Damaged, E - Replace 21,60

