



VOLKSWAGEN Transporter: 507BQB

Vinnnumber:	WV1ZZZ7HZA254230	Versionname:	TRANSP.1000 B/F SWB
First Registrationdate:	7/05/2010	Fiscalpower:	140PK
Expertise Mileage:	108952	Power Kw:	103
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3729
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Rear parking sensors
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	150,00
-------------------	--------

Boot carpet, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, No damage, Acceptable	0,00
-----------------------------	------

No pictures to display

Dashboard, Scratch(es), Acceptable	0,00
------------------------------------	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Spare wheel compartment lining R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Spare wheel compartment lining R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display