


MITSUBISHI Outlander: 1HXX383

Vinnumber:	JMBXLGF6WEZ400716	Versionname:	OUTLANDER 4WD Instyle Safety 150PK Aut.
First Registrationdate:	24/10/2014	Fiscalpower:	
Expertise Mileage:	72177	Power Kw:	110
Bodytype:	MPV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4620
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Seats electric F L	
Windows electric R		Sun Roof electric	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/18/98 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	985,90
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	0,00





Wing R L, Scratch(es), It - Spot repair 115,56



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance book, Missing, E - Replace 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 362,02



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16

