


**RENAULT ESPACE: 1KTK606**

Vinnnumber:	<b>VF1RFC00753159058</b>	Versionname:	<b>1.6 DCI 160 EDC ENERGY INITIALE PARIS</b>
First Registrationdate:	<b>30/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>110203</b>	Power Kw:	<b>118</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3114</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Seats electric F L	
GPS storage	<b>HD</b>	Seats electric F R	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting	<b>Headlighting LED</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/55/19/105 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5,5 mm</b>	Re.R.	<b>Michelin: 5,5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>1970,31</b>
-------------------	----------------

Registration Document, Damaged, E - Replace	<b>150,00</b>
---	---------------



Door F L, Bump(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Door frame F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R R, Bump(s) and scratch(es), It - Spot repair 115,56



Door F R, Bump(s), PDR - Knock out without painting 82,80



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Certificate Of Conformity, Damaged, E - Replace 150,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02





Sill outer R, Scratch(es), It - Spot repair 115,56



Alloy rim F R polished, Damaged, E - Replace 277,44



Instruction book, Missing, E - Replace 0,00

*No pictures to display*