



BMW 1: 1HKV572

Vinnnumber:	WBA1C91040P694484	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	13/08/2014	Fiscalpower:	
Expertise Mileage:	151107	Power Kw:	85
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2607
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1093,68
Alloy rim F L, Damaged, LI - Repair and paint (complete)			95,00



Alloy rim R R, Damaged, LI - Repair and paint (complete)	95,00
---	--------------




Alloy rim F R, Damaged, LI - Repair and paint (complete) 95,00



Bonnet, Bump(s), LI - Repair and paint (complete) 290,08



Alloy rim R L, Damaged, LI - Repair and paint (complete) 95,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



