


AUDI A3: 1FMX190

Vinnnumber:	WAUZZZ8V4EA042848	Versionname:	A3 BER Ambition 140PK
First Registrationdate:	23/08/2013	Fiscalpower:	
Expertise Mileage:	97872	Power Kw:	103
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2306
Number of doors	3		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Sun Roof electric	
Windows electric F		Central consol F	
Seats F heated		Luggage cover	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Xenon	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	1743,64
-------------------	---------

Bumper grille, Scratch(es), Smart repair	110,64
--	--------




Bonnet, Bump(s), PDR - Knock out without painting	63,00
---	-------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00




Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Ignition key, Missing, E - Replace

150,00

No pictures to display