



BMW 3: 1GED674

Vinnnumber:	WBA3Y11060D448212	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	14/01/2014	Fiscalpower:	136PK
Expertise Mileage:	109204	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	DANS 12000KM	Parking lot	2510
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	739,60
-------------------	---------------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Door R R, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Repaired, P - Check 0,00



Door R L, Repaired, P - Check 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s), Acceptable 0,00



Seat cover F L, Worn, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), Acceptable 0,00

