


BMW 5: 1GUR679

Vinnnumber:	WBA5C31090D049216	Versionname:	5 BER 520d 163PK
First Registrationdate:	6/05/2014	Fiscalpower:	
Expertise Mileage:	109864	Power Kw:	120
Bodytype:		Body color	Beige
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2415
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			467,60
Alloy rim F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Sill outer L, Scratch(es), LI - Repair and paint (complete)			372,60





Bumper R, Damaged, Le - Replace and paint 0,00



Alloy rim R R, Damaged, LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 0,00



Ignition key, Missing, E - Replace 0,00

No pictures to display