



CITRO?N C5: 1HEX907

Vinnnumber:	VF7RWRHR8EL511262	Versionname:	C5 TOURER Exclusive FAP
First Registrationdate:	3/07/2014	Fiscalpower:	136PK
Expertise Mileage:	176660	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1410
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining semi-leather	Type of Tow bar	Tow bar fixed
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Bridgestone: 2 mm	Re.R.	Bridgestone: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1450,08
-------------------	----------------

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------




Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18

