


CITROEN Berlingo: 1FHY803

Vinnumber:	VF77B9HN0DJ680243	Versionname:	BERLINGO B/F Kort Fresh
First Registrationdate:	3/07/2013	Fiscalpower:	75PK
Expertise Mileage:	180112	Power Kw:	55
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3312
Maintenance:	- 15000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	No Tow bar
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1677,83

Door frame F L, Bump(s) and scratch(es), It - Spot repair 115,56



Gear shift lever cover, Worn, Acceptable 0,00



Steering wheel, Worn, Acceptable 0,00



Wheel cover F L, Missing, E - Replace

22,50



Rearview mirror housing R, Scratch(es), Smart repair

110,64



Wheel cover F R, Missing, E - Replace

22,50



Rearlight R , Damaged, E - Replace

91,50



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

231,15



Maintenance, Maintenance, Execute

0,00

No pictures to display

Bumper R, Strained , P - Check

0,00



Trunk door panel R, Damaged, E - Replace

25,00



Trunk door R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Missing, E - Replace

22,50



Wing F R, Scratch(es), LI - Repair and paint (complete)

165,13



Wheel cover R L, Missing, E - Replace 22,50



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 361,13



Front bumper, Damaged, E - Replace 398,40



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door panel L, Damaged, E - Replace 25,00



Seat cover F L, Hole, Smart repair 64,32

