



CITROEN Berlingo: 1FH794

Vinnumber:	VF77B9HN0DJ680242	Versionname:	BERLINGO B/F Kort Fresh
First Registrationdate:	3/07/2013	Fiscalpower:	75PK
Expertise Mileage:	173451	Power Kw:	55
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2111
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	No Tow bar
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT 1032,14

Trunk door R L, Bump(s) and scratch(es), It - Spot repair 115,56



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Damaged, E - Replace 22,50



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 232,88



Front bumper, Scratch(es), Smart repair 110,64



Wheel cover R R, Damaged, E - Replace 22,50



Front bumper, Scratch(es), LI - Repair and paint (complete) 158,85



Wing R R, Scratch(es), LI - Repair and paint (complete)

231,15



Wheel cover F R, Damaged, E - Replace

22,50

