



**CITROEN BERLINGO: 1GHA995**

Vinnnumber:	<b>VF77J9HP8DJ882804</b>	Versionname:	
First Registrationdate:	<b>6/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>128894</b>	Power Kw:	<b>68</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2423</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Type of headlighting:	<b>Headlighting Halogen</b>	Type of Tow bar:	<b>No Tow bar</b>
Type of GPS:	<b>No GPS</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/65/15/94 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT 1145,28

Bumper corner R R, Scratch(es), It - Spot repair 115,56



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Interior, Dirty, Cleaning 0,00



Roof, Bump(s), PDR - Knock out without painting 63,00



Bonnet, Bad repair, Acceptable 0,00



Front bumper, Scratch(es), Smart repair 110,64



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Seat cover F L, Damaged, E - Replace 360,00



Wing R R, Bump(s), PDR - Knock out without painting 63,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Dashboard, Scratch(es), Smart repair 110,64



Bumper R, Bump(s), Smart repair

110,64

