



BMW 4 GRAN COUPE: 1NNV078

Vinnumber:	WBA4E91040G391471	Versionname:	2.0 420D (120KW) GRAN COUPE
First Registrationdate:	29/03/2016	Fiscalpower:	
Expertise Mileage:	195638	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1322
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1445,02
Foglight R, Broken, E - Replace	156,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Seat cover F L, Worn, Acceptable 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bump(s), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 513,84



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 458,02



Wing R R, Bump(s), Acceptable 0,00

No pictures to display