



CITROEN C5 BERLINE: 1JLK485

Vinnnumber:	VF7RDRHH4EL518740	Versionname:	2.0 HDI 160 MAN6 EXCLUSIVE
First Registrationdate:	16/01/2015	Fiscalpower:	
Expertise Mileage:	179118	Power Kw:	120
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2112
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	245/45/18/100 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	814,65
-------------------	---------------

Bonnet, Bad repair, Acceptable	0,00
--------------------------------	-------------




Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Armrest R M, Damaged, Smart repair	64,32
------------------------------------	-------



Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------

