



BMW 3: 1GWC050				
Vinnumber:	WBA3D11010F329354	Versionname:	3 BER 318d 136PK	
First Registrationdate:	15/05/2014	Fiscalpower:		
Expertise Mileage:	152479	Power Kw:	100	
Bodytype:	Berline	Body color	Black	
Gearbox:	MAN 6 VIT	Body color	.	
Transmission:	Back	Paint type	Metalic	
Fueltype:	Diesel	Rims summer	Aluminium	
Battery functioning	Yes	Oil level	OK	
Number of doors	4	Parking lot	2830	
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage		Front parking sensors		
GPS storage	HD	Rear parking sensors		
Windows electric F				
Windows electric R				
Steering wheel multifunctional				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Level control				
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT		1278,12		
Door F L, Bump(s), Acceptable		0,00		
				
Wing F R, Bump(s), PDR - Knock out without painting		63,00		

		Roof, Scratch(es), Acceptable	0,00
		Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
		Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
		Door R R, Scratch(es), It - Spot repair	115,56
		Foglight L, Crack, E - Replace	138,00
		Foglight R, Crack, E - Replace	138,00
		Alloy rim F L, Scratch(es), I - Repair	100,00
		Door F R, Scratch(es), 67 - Polish	0,00
		Seat cover R, Stain, Cleaning	25,00
		Wing F L, Bump(s), PDR - Knock out without painting	63,00



Wing R L, Scratch(es), It - Spot repair

115,56

