


CITROEN Jumper 35 MWB: 1JAU381

| | | | |
|------------------------------------|---------------------------------|--------------|--------------------------------------|
| Vinnnumber: | VF7YCTMFB12725418 | Versionname: | JUMPER 35 B/F L2H1 Club 130PK |
| First Registrationdate: | 19/11/2014 | Fiscalpower: | |
| Expertise Mileage: | 193537 | Power Kw: | 96 |
| Bodytype: | Transporter | Body color: | White |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | LCV11 |
| Number of doors: | 6 | | |
| Number of seats: | 3 | | |
| Number head rests: | 3 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|-------------------------------|-------------------|
| Windows electric F | Central consol F | |
| Cruise Control | Rear parking sensors | |
| Steering wheel multifunctional | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|------------------------------|--------------------------|-------|--------------------------|
| | 215/70/15/109 R Steel | | | |
| Summer tyres: | Fr.L. | Continental: 2 mm | Fr.R. | Continental: 2 mm |
| | Re.L. | Michelin: 7 mm | Re.R. | Michelin: 7 mm |

Assistance equipment

| | |
|-------------|------------|
| Spare wheel | Yes |
|-------------|------------|

| | |
|-------------------|---------|
| Total cost ex VAT | 1912,95 |
|-------------------|---------|

| | |
|---|--------|
| Rearview mirror housing R, Damaged, E - Replace | 144,00 |
|---|--------|



| | |
|---|--------|
| Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 232,88 |
|---|--------|





Windscreen, Damaged, E - Replace 0,00



Trunk door panel L, Damaged, E - Replace 50,00



Door moulding Lower R R, Missing, E - Replace 91,50



Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Trunk door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, E - Replace 398,40



Wing F R, Bump(s), LI - Repair and paint (complete) 165,13



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 361,13



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76

