



**FORD Fiesta: 1GWD722**

Vinnumber:	<b>WF0DXXGAKDEJ43004</b>	Versionname:	<b>FIESTA BER Trend ECONetic S/S 95PK</b>
First Registrationdate:	<b>16/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>102298</b>	Power Kw:	<b>70</b>
Bodytype:		Body color	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>3432</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>4</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD	Luggage cover
GPS storage	<b>SD</b>
GPS storage	
Windows electric F	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>175/65/14/82 T Steel</b>			
Winter tyres:	Fr.L.	<b>Fulda: 5 mm</b>	Fr.R.	<b>Fulda: 5 mm</b>
	Re.L.	<b>Fulda: 6 mm</b>	Re.R.	<b>Fulda: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

**Total cost ex VAT**

	<b>254,68</b>
--	---------------

**Bumper R, Strained , I - Repair**

	<b>0,00</b>
--	-------------



**Bumper R, Difference in color, Acceptable**

	<b>0,00</b>
--	-------------



Wheel cover F R, Scratch(es), Acceptable	0,00
------------------------------------------	------

No pictures to display

Bodywork, Not original part, Remove lettering	0,00
-----------------------------------------------	------



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,68
---------------------------------------------------------------------	--------

