



FORD GRAND C-MAX: 1LSJ162

Vinnnumber:	WF0WXXGCEWFM52172	Versionname:	2.0 TDCI 110KW S/S BUSINESS EDITION+
First Registrationdate:	23/11/2015	Fiscalpower:	
Expertise Mileage:	117934	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1431
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 9,9 mm	Re.R.	Uniroyal: 9,9 mm


Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1147,62
-------------------	----------------


Roof, Bump(s) and scratch(es), LI - Repair and paint (complete)	481,50
---	---------------





Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68




Towhook (fixed), Not functioning (well), P - Check

0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bumper spoiler F, Scratch(es), E - Replace

42,00



Dashboard, Scratch(es), Smart repair

110,64

