



**FORD Mondeo: 1EXC201**

Vinnnumber:	<b>WF0GXXGBBGDU04698</b>	Versionname:	<b>MONDEO CLIP Econetic Titanium 115PK</b>
First Registrationdate:	<b>11/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>161230</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>SD</b> Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/16/93 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	681,43
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearlight L, Damaged, E - Replace	228,00



Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------



Reflector, Damaged, E - Replace	38,23
---------------------------------	-------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

*No pictures to display*

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bumper F L, Stone chip(s), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bumper R, Bump(s) and scratch(es), E - Replace	415,20
--	--------

