



FORD MONDEO: 1KSE048

Vinnnumber:	WFOEXXWPCEEG29868	Versionname:	2.0 TDCI 110KW S/S ECONETIC BUSINESS ED+
First Registrationdate:	22/06/2015	Fiscalpower:	
Expertise Mileage:	97523	Power Kw:	110
Bodytype:	Hatchback	Body color:	Dark Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3212
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting LED
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment
















Emergency spare wheel **Yes**

Total cost ex VAT **1700,18**

Roof, Chemical polution, LI - Repair and paint (complete) **481,50**



Ignition key, Missing, E - Replace **150,00**

<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Door R L, Scratch(es), LI - Repair and paint (complete)		318,35
		
		
Wing F R, Scratch(es), LI - Repair and paint (complete)		220,18
		
Sill outer L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Interior, Dirty, Cleaning		0,00
		
		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Seat cover F L, Worn, Acceptable		0,00
		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), LI - Repair and paint (complete)		318,35
