


FORD S Max: 1HGL024

Vinnnumber:	WF0SXXGBWSEU68053	Versionname:	S-MAX ECO Tit.Style DPF PS 163PK Aut.
First Registrationdate:	15/07/2014	Fiscalpower:	
Expertise Mileage:	162235	Power Kw:	120
Bodytype:	MPV	Body color	Light Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2525
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Seats R ventilated	
Cruise Control		Seats F L ventilated	
Steering wheel multifunctional		Seats F R ventilated	
Seats F heated		Panoramic roof	
Radio multimedia		Central consol F	
Type of headlighting	Headlighting Halogen	Luggage cover	
Type of GPS	GPS big screen color	Front parking sensors	
Type of Lining	Lining leather	Rear parking sensors	
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 Y LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	300,64
-------------------	--------

Sill outer L, Bad repair, Acceptable	0,00
--------------------------------------	------



Bumper R, Difference in color, Acceptable	0,00
---	------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Bad repair, Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display
Bumper R, Scratch(es), Smart repair 110,64



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display
Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Maintenance book, Missing, E - Replace 0,00

No pictures to display