



FORD Fiesta: 1EXK926			
Vinnnumber:	WF0DXXGAKDDM85049	Versionname:	FIESTA BER Titanium ECONetic S/S 95PK
First Registrationdate:	15/04/2013	Fiscalpower:	
Expertise Mileage:	119565	Power Kw:	70
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2314
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	175/65/14/82 T LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment	
Emergency spare wheel	Yes

Total cost ex VAT	5544,39
Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44




Door F L, Bump(s) and scratch(es), Le - Replace and paint	894,81
--	---------------



Rear window, Scratch(es), E - Replace	320,00
--	---------------



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 248,40



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Door R R, Bump(s) and scratch(es), Le - Replace and paint 786,33



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 169,44





Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

254,68



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)

176,14



Roof, Chemical polution, LI - Repair and paint (complete)

529,20



Bonnet, Chemical polution, LI - Repair and paint (complete)

328,06



Wing R R, Bump(s) and scratch(es), Le - Replace and paint 1033,21

